
FIG









FIG. 3A

























FIG. 9A




F I G. 9B



## FIG. 10



## FIG. 11



## FIG. 12

URL http://www.maintain.co.jp/db/input.html	
TROUBLE DB INPUT WINDOW	
TOTAL TOTAL CONTRACTOR	
OCCURRENCE DATE 2000/3/15 4040	
TYPE OF APPARATUS ******** ~ 4010	
SUBJECT	OPERATION ERROR (START-UP ERROR) ~ 4030
SERIAL NUMBER S/N 465NS4580001 ~ 4020	
DEGREE OF URGENCY D ~4050	
SYMPTOM	LED IS KEPT FLICKERING AFTER 企 4060
REMEDY	POWER ON AGAIN (PRESS RED BUTTON IN ACTIVATION) 4070
ľ	
PROGRESS	INTERIM HAS BEEN DONE
SEND RESET 4100 4110 4120	
LINK TO RESULT LIST DATABASE SOFTWARE LIBRARY OPERATING GUIDE	

FIG. 13




FIG. 14

